

10.40.

Cook, Welton & Gemmell Ltd., Beverley.

Yard No. 761.

F.E.

Similar to the "ABY" "BULBY" "NAVENA" & "ST. BOTHOLPH".

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME s.s. "JOSENA" Rpt. Ful. No. 53358

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 1862 Depth "d" -

2nd Long. No. 5187 Proportions = $\frac{L}{D}$ 9.5

Framing Angles, as approved Sheerstrake As approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 "Stm Trawler

BK 8", 4BH, Lloyd's A & CP., Cem.

Q 75', F 24'

O.L. 148.0'

E.S.D.

"O"

It is submitted the Surveyors be requested to state the statutory and breaking tests applied to the steering chains.



© 2021

Lloyd's Register
Foundation

009610 - 009620 - 0095

Spacing