

and subse
other caus

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

Enclosures.

17th April, 1951.

Classn(S)
RMC

Dear Sir,

I forward herewith the correspondence on the Lighter "VIC 63" from which you will note that the Warship Production Superintendent, Southern Area, stated on the 3rd instant that the ship is to be drydocked at an early date, but that the overdue Screwshaft and Special Surveys are not to be held.

It will therefore be appreciated if you will kindly take this case up with the Department concerned, with the suggestion that if this information is correct they will be good enough to address a communication to this Office confirming that classification is no longer desired.

Yours faithfully,

Assistant Clerk to
the Classification Committee.

Wm. White, Esq.,
Naval Construction Department,
Admiralty,
Warminster Road,
BATH.



© 2021

Lloyd's Register
Foundation