

DISCLOSED SECTION.

Rpt. S.

No. 496

(Received at London Office)

No. 117889A

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of 496

No. in Reg. Book. 80448 Survey held at on the Wood, Iron or Steel Lighter "VIC 63" Date, First Survey... Last Survey... 19... (No. of Visits...)

TONNAGE :- Built at Northwich By whom Isaac Pinblott & Sons Ltd. When 1945 MONTH 2  
GROSS 141 Owners The Admiralty Owners' Address...  
UNDER DK. 99 Managers...  
NET 52 Port belonging to Liverpool

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...  
Cell DBorDBa feet; uE & B... feet; f... fee  
total capacity... tons. FPT... tons; APT... tons; MT... feet tons.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 123803. Port Lis.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)  
CHARACTER: +100A1 Lighter  
Machinery and Boiler Surveys (Including date of N.B., if any): LMC 2,46  
Coasting Service - Ports TS 06.  
in the V.K. Channel Islands,  
Isle of Man & Eire Fitted for oil fuel  
excluding the West Coast 2,46 F.P. above 150F.  
of Ireland 2,46.  
Cargo battens not fitted else welded.  
Society's Freeboard (if assigned) as ft. ins.  
painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

### PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Planking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors. No. of
Reverse Frames	Have Stulce Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Swingers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting	
Have the Tanks been tested?		State if examined.	

### General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

FRI. 1 JUN 1951


Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

*Delete all particulars write adm on repairs of R-B.*

*Am. for Rep...*



Lloyd's Register Foundation

009640-009646-0113