

Isaac Pimblott & Sons Ltd., Northwich.Yard No.667.

1

Sister vessel to the "VIC 49", "VIC 50", "VIC 51", "VIC 54", "VIC 55",
VIC 79", "VIC 60" etc.

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME Steam Lighter "VIC 63" REPORT Liv. No. 123803For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry. ~~Waste~~

100A1 "Coasting Service - Ports in the U.K., Channel Islands,
Isle of Man and Eire, excluding the West Coast of Ireland".
"Fitted for oil fuel 2,46, FP above 150°F".

1 Dk "Elec. welded"

FPT 30t,

FK, 2BH, Lloyd's A & CP

P 7' Q 19' F 14'

Mchy Aft

O.L. 85.0'

$$\frac{11}{16}''$$

The Certificate of Classification to
be endorsed "Cargo holdens not
fitted" and the same notation to be
printed in the Register Book.

Equipment letter for fees "a" in red.

© 2021

18.3.46.

Lloyd's Register
Foundation

009640-009646-0115