

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 19 When handed in at Local Office 15.10.1906 Port of Glasgow  
 No. in Reg. Book 33 Survey held at Glasgow Date, First Survey and Last Survey 5 Oct 1906  
 33 Supp/the Wood, Iron or Steel S.S. Berne Master  
 TONNAGE:— Built at Dublin By whom Dublin Dockyard 6? When 1906  
 GROSS 1017 Owners J. Harrison & J. Defty (Mgn.) Port belonging to Dublin  
 UNDER DE 769 Owners' Address  
 NET 508 (If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Princes Destined Voyage  
 WB=CellDBorDBa feet; uE&B feet; f feet;  
 total capacity tons. FPT tons; APT tons; MT tons.  
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, girders, and of the inner bottom plating especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of anchors or chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys	Year assigned for survey	Machinery and Boiler Surveys (including date of N.B., if any)
100. A1. (Class Contingent)		

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Completion

The engine & boiler casing has been efficiently closed in & riveted up.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Removed								
Removed and Faired or Repaired								
Painted or Denealed in place								

  

PRESENT CONDITION OF THE	Stringers	Dbing. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fall.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking	Sails
Rivets	Windlass	Treenails	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Breasthooks & Stemson	Anchors, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frametopopenings ditto	" length size (on board)
Reverse Frames		Ditto ditto at other places ditto	" Rule length size (per Table 22)
Floors		Stringers, Clamps & Shells ditto	Hawsers & Warps
Keelsons		Salting ditto	Standing & Running Rigging
		(State if examined.)	

## General Observations, Opinion as to Class, Recommendation, &amp;c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.05," or "to remain as classed and to have record of survey, 1.05, and the notations of ss No. 1-05 and ptND05, &c."

The above is for the information of the Committee

Survey Fee (per Section 20) £ :  
 Special Damage or Repair Fee (if any) £ :  
 Travelling Expenses (if chargeable) £ :  
 Second Surveyor's Fee (if any) £ :

Fees applied for,  
 10  
 Received by me,  
 10

J. H. MacNeill

Surveyor to Lloyd's Register of British & Foreign Shipping.

FRI. 19 OCT 1906

Committee's Minute

Character Assigned For the Committee's information.

Lloyd's Register Foundation

009655-009666-0198