



JW/PK

Lloyd's Register of Shipping,

2, Laidlaw Building,

Battery Road,
(P.O. Box 480),BY AIRMAIL

RECEIVED Singapore, 20th January, 1950.

24 JAN 1950

ANSD.....

Reference

"S"

Dear Sir,

"SENAT"

We have to acknowledge receipt of your Classing Letter of the 28th December, 1949 with its query regarding the equipment of the above named vessel.

We have been in communication with Mr. Millar and with the Owners' Representatives and their replies are attached hereto.

The Owners' Representatives suggest that the equipment as now fitted, i.e. 2 bower anchors, 1 stream anchor and 165 fathoms of chain cable, is in accordance with the B.C. "equipment letter" given in the Register Book and has been approved for the vessel's sheltered trade. Mr. Millar states that this vessel, and all similar vessels, have been regularly reported as having this reduced equipment and that no comment has been made by the Committee of the British Corporation Register.

As the Committee's ruling in this matter will have a bearing on many vessels which are now undergoing or are due for Special Survey, we shall be glad if you will advise us of their decision by airmail.

Yours faithfully,

John Wormald
FOR THE SURVEYORS.

ENCL:

The Secretary,
L O N D O N.




© 2020

Lloyd's Register
Foundation

JMS: M. of Surveyors

Referred to Mr. Perris.

Reddy's High School



John W. ...

memo dated 30-1-50
reply

mer
aplij.

1871

[illegible]

2, Laichow Building,

And a Register of Shipps

© 2020

Lloyd's Register Foundation

FILE ADDRESS "P"
PHONE No. 5
R REF: JTRW:
UR REF:

Dear

Illoyō

in co
para
vess
vess
from

on p
fol

vess
the
diam
a. we
fact
part
to s