

LLOYD'S REGISTER OF SHIPPING

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "SENAI"

Official No. 180437


Port of Registry SINGAPORE

This ship has been under survey at Singapore

on 18th May, 1960. 195 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~—


CREWS TOILET, TWEEN DECK PORT SIDE AFT.

Scupper originally draining to the Engine room bilge now discharging overboard, at tween deck level through two 2" diameter G.M. non return valves on the ship's side, the inner valve being accessible at all times.



Noted
23/7/60

A copy of this Report has been placed on board.



© 2020

Lloyd's Register
Foundation