

1

Sent to Chief Surveyors

Received from Chief Surveyors

25 JUN 1935

VESSEL'S NAME

"BAYRAKLI"

Report

Lon.

No. 103572

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

The 1st S.S.No.1 became due 3,38.

The attached letter has now been received from
new
the Owners' Agents to the effect that the Owners do not
intend to have the vessel registered in the Society's Register
Book.

It is submitted the class of this vessel be
withdrawn from the Register Book and Three Dots (...)
inserted in lieu thereof, indicating withdrawal of class
at Owners' request.

Withdraw class

Insert (...)

RM
24.6



© 2020

Lloyd's Register
Foundation