

7-8 APR 1938

Surveyors _____

Received from Chief Surveyors _____

NAME "NEW DAGENHAM"

Report L.A. No. 5873

For the CHIEF SHIP SURVEYOR and _____

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."--(Extract from Sub-Committee's Report, 24/6/32.)

Survey _____

When due _____

This vessel has now arrived in Turkey.

It is submitted an enquiry be addressed to the Owners ^{asking} ~~requesting~~ them to state if the class of this vessel is to be maintained, and to indicate the service for which it is now intended to employ the vessel, with a view to the necessary alterations being made to the vessel's class.



Handwritten signatures and dates: "20/4/38" and "G.B." with other illegible marks.

Lloyd's Register Foundation