

COPY.

Lloyd's Register of Shipping.

Port LISBON.

29th. January 1938.

This is to Certify that I have

surveyed the ~~Boiler~~ Boiler & Aux Machinery of the Turkish Twin Screw

V. "NEW DAGENHAM" 365 tons gross, No 12025 in the Register Book,

or repairs to damage, x x x x x x x x x x

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

recommended that the record of L.M.C. as recorded, x x x


x x x x x x x x x x

retained ~~made~~ in the Register Book in the case of this vessel.

(Signed) G.T.B. Scullard.

Engineer Surbepor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any error or negligence in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other documents of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or for any error of judgment, default, or negligence of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



009674-009681-0262