

COPY.

Lloyd's Register of Shipping.



Port

BORDEAUX.

No. 4272.

10th. January 1938.

This is to Certify *that I have*

Surveyed the ~~Boiler and Machinery~~ of the Steel Twin Screw Motor Vessel "NEW DAGENHAM", 255 tons gross, No. 12085 in the Register Book, whilst lying in drydock at BAYONNE, on the 11th December 1937 and on subsequent dates, for damage stated to have been sustained through grounding on the BRIQUET ROCKS (near St Jean de Luz), on the 29th November 1937.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended *that ~~the record of~~ no alteration*

be made in the Register Book in the case of this vessel.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
Foundation

009674-009681-0247