

30 JUN 1938

1

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME CorgusRpt. 901No. 11872

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

DAMAGE.

Damage through collision. (901 11762)

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed.....	2						
Removed and faired or repaired.....	3						
Faired or repaired in place.....	3	5					

Other items:-

Vessel placed on floating dock, 4 oil tight bulkhead
plates part renewed, 2 repaired, 1 minor repairs
effected.

Bottom coated.

It is submitted the vessel is worthy to remain as classed with
record of Survey 6,38 without special condition.

100A1

6,38 901

Carrying petroleum
in bulk.

} without etc.



© 2021

Lloyd's Register
Foundation