

Lloyd's Register of British & Foreign Shipping,

Maritime Buildings, East Dock Street,

Dundee, 4th November 1910

Dear Sir,

At the request of the Owners representative, we have today examined the Engine Room of M/V Van Vleet No. 82 (now named London Queen) and find the workmanship very unsatisfactory, the work not being properly closed and the rivets black.

In our opinion the only thing to do, to put some right, is to completely rebuild the Engine Room.

We understand that in all probability Mr. Pitt will be calling upon you regarding this case, so thought it best to let you know the facts of the case.

I am
Yours faithfully,
Wm. Salmon.

R. J. P. Hedges Esq. D. L. E.
London



© 2020

Lloyd's Register
Foundation

009702-009710-0062

009702-009710-0062