

nt to Chief Surveyors.....

Received from Chief Surveyors.....

ESSEL'S NAME "HELGA MOLLER" REPORT - No. -

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey When due

A 3rd S.S. No.2 due 5.43 has not been held.

The ship has an "Examined" record of "8.46" (6 mos.).

The particulars of this case are contained in endorsement dated 4.3.47 and subsequent cablegrams and in view of the latest cablegram received today, IT IS SUBMITTED that this ship's class be expunged from the Register Book with a red line ~~3.47~~ indicating that the character has been expunged on account of non-compliance with the Society's Rules as regards Survey.

Delete from R.B:- Ship's class.

Insert in R.B:- ~~3.47~~

A.



© 2020

Lloyd's Register Foundation

21.3.47.

009702-009710-0163

Final decision
re cable 21.3.47

as }
fied }
al
Oct
tfo
e g
Felt.
th...
c...
certa
iges
nov
ard)
1.
ps.
g and running