

d by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME..... HEIYO MARU..... Rpt. Kob No. 11839

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 1st S.S. No. 3, due 3.42, has been partly held.

The KOBE Surveyors report the vessel placed in dry dock, bottom coated, and the Survey advanced.

Minor repairs effected.

The Owners do not desire to have a fresh record of intermediate docking.

It is submitted the vessel appears worthy to remain as classed with docking date 6.41.

(DOCKING DATE 6.41).



6.41
17-9-41
S.S. PART HELD.

Lloyd's Register
Foundation

009711-009720-011

19 SEP 1941