

5m,10,30.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

16 JUN 1931

VESSEL'S NAME Steel Sc. "ST. FAITH"

Rpt. Ver. No. 2958

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

Ver 1876

The class is subject to the starboard oil fuel tank not being used until repaired.

The Vancouver Surveyors now report the vessel placed in dry dock, bottom coated and on account of damage through grounding 1 shell plate has been faired and repaired and some rivets in a garboard plating renewed and minor repairs effected.

On account of wear and tear a repair has been effected to the steering gear.

It is submitted the vessel appears worthy to remain as classed with record of survey 5.31, subject as above.

A-1
For tanning purposes
5.31 Ver
Fitted for oil fuel etc.

Subject to



© 2021

Lloyd's Register
Foundation
15.6.31.

009780-009788-0182

Stringers	Have Ventilators and their Coamings been examined	Stringers, Clamps & Shells	ditto	Hawser & Warps
-----------	---	----------------------------	-------	----------------