

COPY.

Lloyd's Register of Shipping.




Port Vancouver, B.C.

May 21st, 1931

This is to Certify that I have surveyed the Steam Tug "ST. FAITH" 421 tons gross register of Vancouver on account of striking bottom in Chatham Channel May 8th, 1931. Vessel examined in dry dock. Repairs to shell plating, starboard side, and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have **Recommended** that she be continued as classed with fresh record of survey 5,31, subject to starboard oil fuel tank not being used until repaired, being fit ~~to carry~~ for towing purposes.

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any error or inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



© 2021
 Lloyd's Register
 Foundation

009780-009788-0189