

Lloyd's Register of Shipping,

Westerkade 5 b,

Rotterdam, 19th December, 1950.

(Postbox 701.)

RECEIVED

29 DEC 1950

Ans.....

Dear Sir,

Rotterdam Rpt. 32583 "DIRECTOR MADARIAGA".

In reply to your classing letter of the 17th November, 1950 I regret I have omitted to state in my report 13 to the Committee that in spite of our correspondence with and my representations to the electrical contractors Messrs. A. de Hoop N.V., Flame Proof lighting fittings were installed which are not quite in conformity with our requirements.

I beg to apologize that this discrepancy was overlooked by me in framing my report.

It would be recommendable perhaps to consider instead of replacing the whole of the fittings to replace the rubber bushes used in the flame proof fittings by lead bushes.

For good order's sake I would like to point out that this vessel is already in service in the Argentine and that also the "LA PLATA" (Messrs. P. Smit's Yard No. 597) has been equipped with the same fittings. The latter is also on her way to Argentine.

cc. Yours faithfully,

Copied
Phall

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

009780-009788-0279

MONTAGNARIUS



Orders to be addressed to
SURVEYORS.

6.

