

Rpt. 8

N/N AKRAN

Lon No. 13861 A

Date of writing Report... When handed in at Local Office... Received London... No. of Visits... First Date... 19... Last Date... 19...

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 59402 on the Iron or Steel M.S. S.S. EIKEN MARU. Tons gross 6395. Year 1952 Month 3. Built at... By Whom... Owners' address... Port of Registry... Date of last examn. in Drydock...

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined. Last Report: No. 7947 Port MORE

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Table with 2 columns: SHIP'S CLASS (Date of Special and of Drydocking Surveys, etc.) and Machinery. Includes handwritten 'DISCLOSED SECTION NO. 645'.

Give dates and references to any letters relating to this Report.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined. Freeboard as marked on ship and now verified... Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR... CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS table with columns: Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Inner Bottom Plates, Deck Plates, Beams, Other Items. Rows: Renewed, Removed and Faired or Repaired, Faired or Repaired in place.

Has a Survey also been held on machinery of the Ship? Is Classification Certificate required? If so, to be sent to... Has Interim Certificate been issued?

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

9,00 KOB

Date of Committee... LFRIDAY 14 OCT 1960... Minute... Class withdrawn at Owners request... Noted for Header

GENERAL COMMITTEE 2021 Thursday 10 & 11 November 1960 Classing Committee decision confirmed. Lloyd's Register Foundation 009787-009795-0003