

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

EL'S NAME Wood So. "STARLIGHT RAYS"

Report

Lon.

No.

88424

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/02.)

of Survey \_\_\_\_\_

When due \_\_\_\_\_

The Half Time Survey became due 10,24.

The Aberdeen Surveyors now forward a letter from the Owner's representative, who states he has been informed by the Owner that he does not intend to retain the classification.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owner's request.

Withdraw Class

Insert ...

*Handwritten signatures and initials:*  
- A large signature, possibly "J. D."  
- A signature, possibly "M. J. G."  
- A signature, possibly "C. S."  
- A signature, possibly "R. S."

© 2021

8.12.24.

Lloyd's Register  
Foundation

009827-009838-0124