

Rpt. 8

Port

LON

No. 13126

Date of writing Report

When handed in at Local Office

Received London

Survey held at

No. of Visits

First Date

19

Last Date

19

DISCLOSED
SECTION
No. 635

DISCLOSED
SECTION
No. 635

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

S.S.

"BUNYO MARU"

Tons gross

3769

Built at

By Whom

When

Owners

Owners' address
(If not already in R.B.)

Managers

Port of Registry

Surveyed Afloat or in Drydock

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

6156

Port

Kobe

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

st be reported in the terms of the Rules. The nature and extent of Examinations s (if any) must be stated in detail, the parts examined and their condition being icated. For Annual, Special or other Condition Surveys the Summary of n and Condition on the back of the Report is to be carefully completed and necessary in the body of the Report. Outstanding items to complete the Survey ummarised at the end of the Report. The reasons for Repairs must be stated, account of Damage (the alleged cause of which must be stated) should be separated irs due to other causes, and, besides being detailed in the body of the Report, ummarised in the form below. When, at a Special Survey, the Shell and Deck rilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain replaced or retested the necessary particulars are to be given on Report 8(Eq) be attached to this Report.

and references to any letters relating to this Report

SHIP'S CLASS
Date of Special and of Drydocking Surveys, etc.

Machinery

cases where the Surveyor has not made a special damage report he should state whether he offered

ices for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft

ins

Was a damage report made by anyone else? If so, by whom?

ATION AND REPAIRS AS PER RULE FOR

CONTINUATION OVER/OR SHEET 2

	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
RY OF DAMAGE REPAIRS								
ed								
ed and Faired or Repaired								
or Repaired in place								

urvey also been held on machinery of the Ship?

Is Classification Certificate required? If so, to be sent to

he Report sent now, or when will it be sent?

Has Interim Certificate been issued?

AL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

tate clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 55, and the notation of S.S. . . . 1.55".

Surveyor to Lloyd's Register of Shipping

Date of Committee

FRIDAY 23 JAN 1959

Minute

Minute 1/56

Class with drawn
d. Owners request

Noted
for
Header

GENERAL COMMITTEE

Thursday, 29th January, 1959
Classing Committee
decision confirmed.

40m/3,58 T.

009860-009868-0214