

Received from Chief Ship Surveyor.....  
20 NOV 1958

SHIP'S NAME "BUNYO MARU" REPORT Kob. No. 6156.  
AR.

Outstanding Conditions of Class: Subject to 90 fathoms of chain cable on board being fitted with end links, retested and refitted at the earliest opportunity.

Endorsement of Certificate (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (B) due 10,58. Postponement until <sup>2</sup>11,59 approved, it being concluded the condition of class with regard to equipment is being dealt with at this time.

Nature of Present Survey: (Afloat ~~and in dry dock~~)

General Examination.

Special Features: The Owners state that 6 new lengths of chain cable have been ordered and will be placed on board during February 1959.

Is Interim Certificate in order (~~Yes or None~~)

Items Outstanding: (If any for S.S.) All

S.S. to be completed by: See Committee Minute

Recommendation: SUBJECT as above but ACTION IS DEFERRED for S.S.

As now. Subject.

S.R.L. APPENDIX.

Shell plate F.3 (s.s.f) indented.

IT IS FURTHER SUBMITTED the Owners' request to postpone the S.S. until 11,59 merits the favourable consideration of the Committee. 2.



© 2021

Lloyd's Register  
Foundation