

COPY

Ship's name

LOCH FRISA

Port

QAK.

No.

77258

Last survey date

12.4.63

Class is subject to

NIL

Docking, screwshaft examined. Bearings: "017"

MBS. due 6.62. partly held 10.62 now completed.

Vessel has been laid up since 10.62 at Greenwich and at this time the boiler was examined internally and found to have been maintained in a good condition. The safety valves have now been adjusted under steam and oil burning system examined.

Inspection returned to makers and repaired and now refitted satisfactorily.

It is submitted that this vessel is eligible to remain as CLASSED.

with fresh records in TS. log) 4.63 and MBS. 4.63 now.

C. J. H. 18.5.63



© 2021

Lloyd's Register Foundation

009879 - 009887 - 0008