

Received from Chief Ship Surveyor

29 OCT 1957

SHIP'S NAME

"BAJAN"

REPORT

Dt.

No.

5175

Outstanding Conditions of Class:

(reinforced 7,56) being specially examined next drydocking. Subject to sternframe solepiece

Endorsement of Class (B) ~~(as before)~~ None)

Nature of Present Survey: ~~(as before)~~ in dry dock)


Minor repairs.

Recommendation:

SUBMITTED NOTATION of 'DS 7,57' be assigned, subject as above.

DS 7,57 Subject

IT IS FURTHER SUBMITTED the Surveyor be advised of the conditions of class and be informed it is concluded that the sternframe was examined, continues efficient and that no alteration is required to the S.R.L.



Lloyd's Register
Foundation

13.11.57
Sel
J.M.
13.10.57