

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

5175



Port Djakarta

22nd September 1957.

This is to Certify *that I have*


Part

Surveyed the ~~Boiler~~ and Machinery of the m.v. "Bajan"

No. 02961 in Reg. Book 57/58, for Annual Condition survey in
drydock on the 23rd July '57 at subsequently


and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of this vessel remains as
classed.

be made in the Register Book in the case of this vessel.


Engineer Surveyor to Lloyd's Register

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

B.1.) 50m,6,55. (MADE AND PRINTED IN ENGLAND)



Lloyd's Register
Foundation

009888-009895-0115