

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 3551 (6 Lines)

Enclosure

25th February, 1954.

Dear Sirs,

Steamer "LISS"

Classn(S)

AH

I acknowledge receipt of your letters of the 13th and 15th instants, the contents of which have been noted.

This case has now received the consideration of the Committee, who have given instructions for the hull and machinery class to be withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at the Owners' request.

The Owners request that the classification of the boilers be continued has been approved and the appropriate notation will be inserted in the Register Book on satisfactory completion of each Annual Boiler Survey.

A copy of the report of the survey of the port and centre boilers which was carried out at Trinidad in September last is enclosed for transmission to the Owners, who should be informed that the port boiler safety valve spindles and main stock valve were reported to be defective, and it was previously recommended that they be renewed by October, 1953.

Yours faithfully,

Assistant Clerk to the
Classification Committee.

The Surveyors,
STOCKHOLM.



© 2021

Lloyd's Register
Foundation