

The class is subject to put boiler safety
valve spindles & main stop valve being
renewed by 10.53

4 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EES NAME

Liss

REPORT

No.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement is to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

It is submitted the owner be advised in
the terms of endorsements 18/9/53 & 2/10/53
& requested to state when ^{absolute port} facilities can
be opened for the application of Genvar 1994
in order that the survey may be fully
advised



© 2021

Lloyd's Register
Foundation

5-10-53