

2 E

18 AUG 1954

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "CACHALOTE" REPORT L.A. No. 1649

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/52.

Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS

This Survey, due 12,52 ~~now~~ partly held 1,54 now completely ~~now~~ held

~~completed~~ and the following repairs carried out (due to wear & tear):-

A number of plain tubes and air heater tubes renewed. Minor repairs and adjustments carried out to the main engine crankshaft and rings. Some repairs have now been carried out to the condenser and arrangements have been made for all tubes to be renewed at a suitable opportunity.

*Screw shaft examined.*

It is submitted the vessel is eligible to remain as classed, with

tation of

Blr.S 4,54

as recommended.

*S. 4.54*

009924-009933-0236

17.8.54

