

Are they fixed sufficiently high on the ship's side to be seen without tilting the platform plates

Yes

Are the Blow Off Cocks fitted with a spigot

How are they protected

Have they been tested as per Rule

Info: "Olympia Maru."

Reg. 1603.

It is submitted that
this vessel is eligible for

THE RECORD.

+ LMC 8.27. CL.
Oil Engines. 2 SC. 5A. 582 NH.
6 Cy. $23\frac{5}{8}$ " - $41\frac{3}{4}$ " DB. 100 lb.

J. W. D.
12/10/27.

© 2021

Lloyd's Register
Foundation

Seamless, lap welded or riveted longitudinal joint.

Starting Air Receivers, No.

One

Total cubic capacity

009434-009442-0303

Seamless, lap welded or riveted longitudinal joint. T.R.D.B.S. Material

Steel.

Range of tensile strength

28-35 ton W. and 25 to 30 ton