

2m.10.39.

DISCLOSED
SECTION.

No. 353

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

24 MAR 1941

VESSEL'S NAME

Ottawacan Maru

Rpt.

Kob

No.

11716

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/192.)

Nature of Survey

DAMAGE.

Damage through

heavy weather

How repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Beams	Inner Bottom Plates	Deck Plates
Renewed							
Moved and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

In drydock, bottom coated
Repairs to bulwarks, deck plating & beams etc
(as per plan attached)

Wear & tear Minor repairs

When submitted the vessel is worthy to remain as classed with

Record of Survey 1.41

D.A.

Sarr. Pet in Bulk

1.41 Jama

20-3. 41



© 2021

Lloyd's Register
Foundation

009934-009942-0318

State clearly whether any repairs have been made and if so, what repairs have been made and to what parts of the vessel. This survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of survey, 1.24" or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24.