

COPY

LLOYD'S REGISTER OF SHIPPING



Port of NAPLES

14th May, 1962

We
 Port & Centre Boilers This is to Certify that I have
 Surveyed the Machinery of the S/S "SAINT EDMUND" (now- "Lucrino")
 7174 tons gross of London, whilst afloat and in Drydock, at
 this Port on the 24th April, 1962 and subsequently,
 and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will Recommend that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book
 MBS. 5/62, on completion of Survey

and that her Machinery Classification Record be continued in the Book.
 without special condition to outboard independent feed pump.

~~XXXXXXXXXXXXXXXXXXXX~~
Parts now examined:
 (C.S. Items only)

NOTE :- To complete the Main Boiler Survey for the fresh
 record 5.62 the Starboard Boiler remain to be
 examined in its entirety.

Carlo Stare *E.F. Butler*
 (C. Stare and E.F. Butler)

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

009943-009953-0169

