

# FOXALL & SONS LTD.

(Founded 1891)

DIRECTORS:  
L. C. PATTERSON  
M. L. PATTERSON  
G. PAGE

AIN TESTING AND ANNEALING.  
TING TACKLE OVERHAULED TO  
ACTORY ACT REQUIREMENTS



S. T. BONITA.

TELEPHONE: ROYAL 6882

33-35, MERSEY STREET,

LIVERPOOL 1

COPY OF MAKERS CERTIFICATE.  
PER LLOYDS REQUIREMENTS.

<u>Material.</u>	<u>Proof Load.</u>	<u>Breaking Load on Test Sample</u>	<u>Equivalent Extension on 36" Test Sample.</u>	<u>Energy Absorption Factory in Tons</u>
diameter exact Tensile Elect- y Welded Steel to BSS.1663.	2 $\frac{1}{4}$ -tons	5-Tons 18-Cwts.	9"	53.1

Normalised to 870° Centigrade.

## MAKERS

HENRY WOOD,  
SALTNEY,  
CHESTER.

pool Lighterage Co.Ltd.,  
Dock,  
pool 1.



© 2021

*ms*  
Lloyd's Register  
Foundation

009943-009953-0200