

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760

RE-CONSTITUTED 1834

## Certificate of Class

Steel Screw Motorship "BEDFORD"  
Official Number 185919 Port of Registry London  
Owners Blandford Shipping Co., Ltd.,  
Builders, and where and when built Lithgows Ltd., Port Glasgow, June, 1953

### REGISTERED PARTICULARS

Length	534.3 feet	Tonnage, Gross	12578
Breadth	74.0 feet	Ditto under Deck	11328
Depth	37.6 feet	Ditto Net	7306

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 29th June, 1953 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1 Carrying Petroleum in Bulk

subject to Periodical Surveys as required by the Rules.


Part Electrically Welded.


Longitudinal Framing.

The approved minimum freeboards from the deck line are as follows:—

Tropical	7 feet 5½ inches (T).	Winter	9 feet 1¼ inches (WNA).
Summer	8 feet 1 inches (S).	Allowance for fresh	
Winter	8 feet 8½ inches (W).	water for all freeboards	8 inches

Witness my hand,

  
R. Hadden  
Secrétaire

  
R. Hadden  
Chairman.

71, Fenchurch Street, London, E.C.3. 30th July, 1953.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”



Lloyd's Register  
Foundation