



LLOYD'S REGISTER OF SHIPPING

SEDE CENTRALE: 71, FENCHURCH STREET, LONDON, E.C.3

Ufficio Principale per l'Italia

Via Sottoripa, 14/112 - Genova (327)

Casella Postale (P. O. B.) 232

Telefoni N.ri: 290.741 - 290.742

Telegrammi: Surveyors, Genova

RECEIVED

27 NOV 1959

Genoa, 25th November, 1959.

Reference

ssf.(S)

Dear Sir,

M/S " EL KARIM "
Renamed " ROSA GAROLLA "

In reply to your letter of the 20th with reference to the classification of the above ship with the Registro Italiano I have made enquiries from the Registro and have to-day cabled you as follows :-

"REURLET EL KARIM RENAMED ROSA GAROLLA VESSEL NOW UNDER RI SURVEY NAPLES STOP RI STATE STARBOARD TAILSHAFT WILL BE RENEWED AND CIRCULATING PUMP BODY RENEWED OR REPAIRED THIS TIME STOP ONLY ONE CYLINDER LINER FOUND TO REQUIRE RENEWAL HOWEVER STOP OUTSTANDING ITEMS YOUR LETTER THEREFORE NOT YET FULLY DEALT WITH LETTER FOLLOWS =
BOYLAN "

Ing. Santagiustina of the R.I. informed me that this ship is under survey at Naples and it is hoped to complete the classification on this occasion. It is intended to renew the starboard screwshaft but no decision to renew the circulating pump body has been made yet because it is considered at least possible that satisfactory repairs could be effected.

The R.I. Surveyors have reported also that only one cylinder liner has been found in a condition which requires renewal.

On learning that all the cylinder liners of both engines had been condemned by the Society's Surveyors however, Ing. Santagiustina stated that he would be very grateful to know the reason for this decision in case something has been overlooked by their Surveyors at Naples. He was informed that copies of the relative reports have been handed to the Owners but apparently

010004-010011-0012/12

Lloyd's Register
Foundation

- 2 -

these have not been produced to Registro Italiano.

Yours faithfully,

The Secretary,
London

J. W. Boylan.

PRINCIPAL SURVEYOR FOR ITALY

FNB:mb



© 2021

Lloyd's Register
Foundation

0012 2/2

CLASSIFICATION

H

AM

2/12/59.

dm:BM



© 2021

Lloyd's Register
Foundation