

to Chief Surveyors _____

Received from Chief Surveyors - 5 OCT 1928

VESSEL'S NAME Steel Sq. "PASSAT" Report Lon, No. 93093a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Age of Survey _____ When due _____

This vessel requires to be examined in dry dock and permanent repairs effected on arrival at a home port.

The 1st S.S. No.2 became due 7,28.

In reply to enquiry the Owners state they intend to obtain the class of the Germanischer Lloyd and request that the class be expunged from this Society's Register Book.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners request.

Withdraw class.

Insert ...

[Handwritten signatures]
3.10.28.
[Handwritten initials]



© 2021

Lloyd's Register Foundation

010012-010023-0073