

COPY

Ship's name "CAIRNGORM"

Port

Gls.

No. 93971

Last survey date 14.9.62

GB Class is subject to

NONE.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and in drydock)

Docking: Temporary repairs on account of damage, cause unknown.


Recommendation

NOTED.

SUBJECT to keel plate No.2 from aft and F.P.bulkhead being specially examined and dealt with as found necessary by the next drydocking.

IN S.R.L. APPENDIX.

Indented shell plates G.1 & 2 (p.s.f).  
Keel and 'A' strake landing (p.s.) set up about 1"  
over a length of 20 ft.



© 2021

Lloyd's Register  
Foundation