

by Chief Ship Surveyor

Received from Chief Ship Surveyor 126 JUL 1950

EES NAME 'S A R O N T A' REPORT Hul. No. 56664

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The HULL Surveyors report (6.50), ship examined on slipway, bottom coated, and a Periodical Special Survey (C) due 11.49 commenced, see report.

TO COMPLETE THIS SURVEY :- See Report, which includes a number of recommended repairs due to wear and tear deferred.

From correspondence attached it would appear that the Special Survey will not be carried out by the present Owners, and the ship remains laid up.

IT IS SUBMITTED ACTION be DEFERRED for completion of Special Survey, but record of docking ~~8.80~~ 12.49 be assigned, and record of "Laid up pending Survey" be inserted in the Register Book.

12.49
Hul.

INSERT IN R.B.

"Laid up pending Survey"



© 2011

S.S. Part Held.

Lloyd's Register
Foundation

010056-010066-0302