

COPY OF AIR LETTER.

TEL

LLOYD'S REGISTER CLASSIFICATION

UNITED WITH THE BRITISH CORPORATION

71, Fenchurch Street, E.C.3

26th January, 1951.

Dear Sirs,

Glassn

EJB

10204, 207, 218, 223, 237, 246, 257. As recommended.

10240 "FOO MING" As recommended. I shall be glad if you will furnish particulars of the cause and nature of the damage to No.3 sheerstrake plate (s.s.a.) as this item is not mentioned in the body of your report.

RMC 10260. As recommended.

"COLON" Contents of your Rpt.10 dated 6.11.50 in respect of an examination of the bottom and shall plating with a view ~~to~~ to recommendations for repairs for contemplated re-classification of this vessel have been noted. No action has been taken in the meantime, and it is concluded that you will keep me advised of any future developments.

Yours faithfully,

pro Clerk to the Classification
Committee.

The Surveyors,
HONG KONG.



© 2021

Lloyd's Register
Foundation