

11th July, 1961.

KOBE

8876, 98, 9032, 41, 47, 67, 94, 97,
114, 20 - As recommended.

RMC 8953, 78 - As recommended.

9034 "SANUKI MARU" - As recommended, except that the notation
ABS 5.61 has been assigned.

9058 "TAMON MARU" - As recommended. It is concluded that both
boilers were examined at this time, but your confirmation is desired.



© 2021

Lloyd's Register
Foundation