

"NANG SUANG NAWA"

Bgk. 1705

Before this case receives consideration IT IS SUBMITTED  
the Bangkok Surveyor be requested to forward a copy of the  
second page of his Rpt. 10 dated 24th February 1954 as this  
has been inadvertently been mislaid.

*checked*

The Surveyor should also be requested to state what  
arrangements the Owners propose making for the defective  
boilers to be dealt with.

*[Signature]*

18.3.54.

*[Signature]*

*Write Bgk  
Rc X 23/3*



© 2021

Lloyd's Register  
Foundation