

"Surveys Overdue" recorded in R.B.

Received from Chief Ship Surveyor

20 MAR 1953<sup>R.C.</sup>

SHIP'S NAME NANG SUANG NAWA. REPORT BGK. No. 1623.

*This ship is classed BS\**

standing Conditions of Class: *Subject to a lower anchor being supplied at the earliest opportunity.*

ersement of Class (B) (~~As before or~~ None)

re of Present Survey: (Afloat and in dry dock)

*Repair to shell plating.*

endation: *Submitted ship is eligible to have record of*

*recking 1.53 and notation of A.S. 2.53 assigned, subject as above*  
BGK. } *Subject.*  
2.53 }

*It is further submitted,*  
*the Surveyor be advised it is concluded ~~it is in error~~*  
*in reporting 200 fathoms of chain cable on board as the*  
*ship was originally equipped with 240 fathoms & as*  
*there has been no loss reported recently.*  
*Delete from R.B.*  
*"Surveys overdue"*

*Gully*