

21 MAY 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME....."MACASSAR MARU".....Rpt. ....Kob .....No. 11759

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to 15 fathoms of chain cable being supplied at the earliest opportunity.

The KOBE Surveyors report the vessel placed in dry dock and the bottom coated.

The Owners state that it has not been possible to obtain a length of chain cable.

It is submitted the vessel appears worthy to remain as classed without record of survey as recommended, subject as above.

As Now, Subject, etc.

(Docking date)



© 2021

Lloyd's Register  
Foundation

010103-010114-0141