

BOARD REPORT on the Blackbird C

report C11 has been examined and found to be  
order excepting for:

The thickness of the ventilation coverings to be reported.

particulars of the prebendal dk men holds to be reported

6 method of fastening the steel hatch covers on the subboard etc. and trunk top etc. to be reported.

K. L.  
29/1/60.

## 7<sup>th</sup> SHIP REPORTS.

Feb

Noted. 24. 29/1/60.



Lloyd's Register  
Foundation

010137-010149-0026

Used Machinery Casings on Free-