

1 SEP 1945

29 - 8 45.

29 - 8 45.

M A L M Ö

M A L M Ö

11th Aug.

25th Aug.

45.

XXXXXXXXXXXX

M/T "S Y S L A" ex. "Kathrine Stenersen"

Malmö

Kockums Lek. V. A.-B.

See recommt

Malmö

Kockums Mek. V. A.-B.

" "

~~Stenersen Transport & Ship Co~~
~~Waggon- & Maskinfabrik A/S~~

~~Hagbe Waage~~

J. Stenersen

Oslo

Afloat

Compl. of 1st Entry

+100Al Carrying

Petr. in Bulk

Plans
(Contemplated)

oil Eng

Yes

11th August, 1945.

Good

172 lbs/sq."

XX

Yes

Yes

Yes

Complete.

Now done:- No. 5 main engine cylinder, cylinder covers with valves, pistons, piston rod, connecting rod with top and bottom end brasses, crosshead, crank pin and crank shaft journal with top bearing examined and found in good condition.
The main and aux. engines and pumps tested under working conditions during a trial in the Sound and found working satisfactory.
The valves of starting air receivers adjusted to the safe working pressures.
Both donkey boilers examined internally and found in good condition and the safety valves adjusted under steam as above.

(To be continued)


The machinery of this vessel is eligible, in our opinion, to be classed in the Register Book of this Society with record of +LMC 8.45. (Please see Malmö First Entry Report No.2156 of the 14th May, 1943).

10% of First Entry	Kr. 11:40
10% of SS dur.constr.	263:91
" " 2 start.air rec.	11:97 29-8 45.
" " 2 donkey boilers	35:72
" " elec.installation	85:03
" " testing forgings	4:-
Cond.Surv.fee	100:-

TUES. 23 OCT 1945

See minute on memo. F.E. rpt. 2156.

A. Boring & Co



© 2021

Lloyd's Register

01071-01078-01032

Sp. Surveyor's Office, Malmö

M/T "S Y S L A" ex. "Kathrine Stenersen" of Oslo.

The safety valves of La Mont boiler adjusted to the safe working pressure.

All tests required by the Rules regarding electrical installation have been carried out with satisfactory results.

Copy of Cert.B1 issued in this case is enclosed herewith.

The vessel has now proceeded to Gothenburg where the screw shaft will be examined. The Surveyors at that port have been informed accordingly.



© 2021

Lloyd's Register
Foundation