

1

8 - MAY 19

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME..... "NITIRYU MARU"..... Report..... Lon..... No..... 109084a

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey..... When due.....

The class is subject to the sternframe (E.W. 9.27, O.A. 11.28, E.W. 5.34, 6.35 and 7.36) being specially examined at the next dry docking.

The 2nd S.S. No. 2 became due 6.40, and it was proposed to deal with this in December last.

The Kobe Surveyors now forward a letter from the Owners intimating their decision to withdraw the vessel from class.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book and three dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class  
Insert ...



Lloyd's Register  
Foundation

W