

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "NITIRYU MARU".

Rpt. Smk. No. 2538.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey ~~=COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 11,39 ^{now} ~~partly~~ held; engines examined. ~~now~~
~~completed~~, and the following repairs carried out (due to wear and tear):-

Front end plate in port boiler(cracked) now repaired by welding and
 some minor repairs effected.

It is submitted the vessel is eligible to remain as classed, with
 notation of ~~ELM~~C12,39, S11,39 as recommended.

© 2021 *GRM*

8/2.40.
 Lloyd's Register
 Foundation

010189-010199-0039