



LLOYD'S REGISTER OF SHIPPING

RECEIVED

- 2 JUN 1958.

20, Sathorn Road, Bangkok
26th May, 1958.

Ans'd

D. C. KNOTT, B.Sc.
SURVEYOR

Reference

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
London, E.C. 3.

Dear Sir,


undelivered
Lighters M.L. 1 & M.L. 3.

These lighters are again in the process of sale, and the new buyers would like them to be reclassified. These vessels were classed before the war, and went through a very big repair 18 months ago, and have not been used since. I would be much obliged if you would let me know if they can be reclassified and what extent will be required to put them into class.

When the sale is completed the Changnam will be docked for tailsaft and boiler survey.

Yours faithfully,

D.C. Knott
D.C. Knott.



Ans'd
②

SR

See Memo. of 4.6.58.



© 2021

Lloyd's Register
Foundation