

CALLERS TO  
SEE TO  
RECEIPTS.



# Lloyd's Register of Shipping.

SEDE: 71, FENCHURCH STREET, E.C., LONDON.

Calle de Ibanez de Bilbao No. 22,

4th Storey,

LLOYD'S REGISTER

LONDON

11 SEP 1922

Bilbao, 6th September, 1922

REC'D  
AUG 11

BYCERS:  
NGLEDOW.  
SKINLAY.  
WLING.  
RAZA.

Dear Sir,

We beg to acknowledge receipt of your classing letter of the 1st, inst, respecting the steamer "MARI" our report N°6032, and in reply we beg to state that I regret the omission in the report of the thickness of plating in holds which is  $\frac{15}{40} - \frac{13}{40}$  .., the butts of the turret stringer plate are in vessel quadruple riveted.

Regarding the equipment we have to state that a 4 1/2" circumference steel wire 90 fathoms long is on board, also four pieces 90 fathoms of 7" diameter Manila hawsers.

We are, Dear Sir,

Yours faithfully,

*J. de Berastain*  
For Surveyors,

The Secretary,

LONDON.



© 2021

Lloyd's Register  
Foundation

010219-010228-0084



in the year 1800

PROBABLY

1942 in  
Bibliography  
and redemptive  
1942 in

© 2021

Lloyd's Register  
Foundation

Referred to the Chief Ship Surveyor.

Also for Mr. S. A. Hill to note.

11 SEP 1922

pieces 20 inches or 24 diameter minus 15wale.  
No 21's best 21'

Учредитель

STORRETT  
1850

THE SECRETARY,  
LONDON.

٢٩

ELEPHO

H. G.

56

## APPOINT

COMM

Dea1

121

pat

55 Ma