

EA

12 MAR 1963

Ship's name "AKAMAS"

Port

EAL

No.

14347

Last survey date 1.2.63.

Class is subject to

a bower anchor being supplied
at the earliest opportunity.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and ~~in drydock~~)

Damage repairs - hoisting anchor.
Equipment - supply and verification of 2 bower anchors
and 15 fathoms of chain cable - see also above.

Recommendation

SUBMITTED the ship is eligible to remain
as classed, without special conditions.

As Now Without.

IN S.R.L. APPENDIX.

Shell plate E.2 (p.s.f) set up.



© 2021

Lloyd's Register
Foundation
to note.

S.H.L.
21-2-63. ✓