

Rpt. 8

DISCLOSED
SECTION

FOR DRAFT PURPOSES ONLY

Port

Lon A.

No.

169550

Date of writing Report

No. 667

When handed in at Local Office

Received London

Survey held at

No. of Visits

First Date

19

Last Date

19

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

82532

on the Iron or Steel M.S.

S.S.

ARRELLA

Built at

By Whom

When

Tons gross

404

Year

1944

Month

4

Owners

Owners' address

(If not already in R.B.)

Managers

Port of Registry

Surveyed Afloat or in Drydock

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

2848

Port

MLV

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS
Date of Special and of Drydocking Surveys, etc.

Machinery

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft

ins

Was a damage report made by anyone else? If so, by whom?

MINATION AND REPAIRS AS PER RULE FOR

CONTINUATION OVER/OR SHEET 2

Inner Bottom Plates	Deck Plates	Beams	Other Items

quired? If so, to be sent to

ed?

the Register Book consequent upon this survey; for example:—
"55"; or "to remain as Classed and to have record of drydocking

Surveyor to Lloyd's Register of Shipping



© 2021

Noted
for
Header

Lloyd's Register
Foundation

010229-010235-0071